

Axcelerator Family FPGAs Errata


Some errors were found in the Axcelerator data sheet. The corrections, noted below, will be incorporated into a revised version of the data sheet. The changes in the graphics are indicated in red font. Within the body, corrections are in bold.

Page 1

- Under Leading-Edge Performance, the fourth bullet should read **700Mb/s** LVDS Capable I/Os.

Page 16

- In the figure, the value for the capacitor on the right is incorrectly shown as 100 μ F. The correct value is **0.1 μ F**.



Page 68, Axcelerator Clock Management System

- In this section, it is not clear that REFP can be configured as single-ended or voltage-referenced standards. In the 2nd column, paragraph three, the last sentence should read: "In particular, the REFP pad can be configured as a differential pair, single-ended or voltage-referenced standard. The REFN pad can only be used as a differential pair with REFP."
- The capacitors' values are incorrectly stated as 10pF and 100-250pf. The correct values are 0.1 μ F and 10 μ F. In the 2nd column, paragraph two, the fourth sentence should read: "Furthermore, **0.1 μ F** and **10 μ F** decoupling capacitors should be connected across V_{CCPLL} and $V_{CompPLL}$ pins."
- The resistor value is incorrectly stated as 100-200 Ω . The correct value is 250 Ω . In the 2nd column, paragraph two the third sentence should read: "The V_{CCPLL} pin should be connected to a 1.5V power supply through a **250 Ω** resistor."
- Figure 33 incorrectly shows the capacitors' values as 10pF and 100-250pf. The values should be **10 μ F** and **0.1 μ F**. See corrected figure below.
- Figure 33 incorrectly shows the resistor value as 100-200 Ω . The correct value is **250 Ω** . See corrected figure below.




Figure 33 PLL Electrical Interface


Page 70

1. In the PLL Signals table in the third body row the function of the PowerDown signal is incorrectly stated as When “high” powers down the PLL. The correct function is “When **low**” powers down the PLL.” Note that the table below is only a portion of the entire table.

PLL Signals

Signal Name	Type	Function
RefCLK	Input	Reference clock for PLL.
FB	Input	Feedback port for PLL.
PowerDown	Input	When “ low ” powers down the PLL.


2. In the interface block diagram one of the signals is shown incorrectly as REFD. It should be **REFN**.


Page 71

1. Under “Power Down” it incorrectly states that the PLL includes an active-high power down signal. It sentence should read: “The PLL also includes an **active-low** power down signal and consumes very little standby current in this mode.”

Page 75

2. In the timing waveform diagram, the PowerDown signal is drawn incorrectly. The figure below shows how it should appear.



Actel and the Actel logo are registered trademarks of Actel Corporation.
All other trademarks are the property of their owners.



<http://www.actel.com>

Actel Europe Ltd.

Maxfli Court, Riverside Way
Camberley, Surrey GU15 3YL
United Kingdom

Tel: +44 (0)1276 401450

Fax: +44 (0)1276 401490

Actel Corporation

955 East Arques Avenue
Sunnyvale, California 94086
USA

Tel: (408) 739-1010

Fax: (408) 739-1540

Actel Asia-Pacific

EXOS Ebisu Bldg. 4F
1-24-14 Ebisu Shibuya-ku
Tokyo 150 Japan

Tel: +81-(0)3-3445-7671

Fax: +81-(0)3-3445-7668